

MSU: Greenwood Lab School (GLAB)

Sample #	Sample ID	Outlet Type	Location	Location Specific	Initial Sampling Date	Initial Sampling Time	Lead Results	Remediation
							200.8 Method ug/L (ppb)	
1A	01A-GLAB-WF-200	Water Fountain	200 Hallway	Southern wall, halfway down 200 hallway, bubbler	3/13/2024	0712	<1.00	No remediation required. Monitor per statutory requirements.
1B	01BHGLAB-WF-200	Water Fountain	200 Hallway	Southern wall, halfway down 200 hallway, bottle filler	3/13/2024	0713	<1.00	No remediation required. Monitor per statutory requirements.
2A	02A-GLAB-WF-300	Water Fountain	300 Hallway	Near entrance, northern end of 300 hallway, bubbler	3/13/2024	0716	<1.00	No remediation required. Monitor per statutory requirements.
2B	02B-GLAB-WF-300	Water Fountain	300 Hallway	Near entrance, northern end of 300 hallway, bottle filler	3/13/2024	0717	<1.00	No remediation required. Monitor per statutory requirements.
3A	03A-GLAB-WF-105	Water Fountain	100 Hallway	South wall, across from room 105, bubbler	3/13/2024	0718	<1.00	No remediation required. Monitor per statutory requirements.
3B	03B-GLAB-WF-105	Water Fountain	100 Hallway	South wall, across from room 105, bottle filler	3/13/2024	0719	<1.00	No remediation required. Monitor per statutory requirements.
4A	04A-GLAB-WF-119	Water Fountain	100 Hallway	South wall, across from room 119, bubbler	3/13/2024	0721	<1.00	No remediation required. Monitor per statutory requirements.
4B	04B-GLAB-WF-119	Water Fountain	100 Hallway	South wall, across from room 119, bottle filler				Not Applicable. Bottle filler component not present on this fountain.
5	05-GLAB-F-133	Faucet	Room 133 (Lounge)	Southwest corner	3/13/2024	0723	<1.00	No remediation required. Monitor per statutory requirements.
6	06-GLAB-F-K-MID-L	Faucet	Kitchen	Middle wall, behind serving area, left fixture	3/13/2024	0726	24.9	Replace lead containing components and retest per statutory requirements
7	07-GLAB-F-K-MID-R	Faucet	Kitchen	Middle wall, behind serving area, right fixture	3/13/2024	0727	3.64	Replace lead containing components and retest per statutory requirements
8	08-GLAB-DW-K	Dishwasher	Kitchen	East wall of dishwashing area	3/13/2024	0737	3.13	No remediation required. Monitor per statutory requirements.
9	09-GLAB-SPRAY-K	Faucet - Sprayer	Kitchen	Southeast corner of dishwashing area	3/13/2024	0731	1.45	No remediation required. Monitor per statutory requirements.
10	10-GLAB-F-K-W-L	Faucet	Kitchen	West wall of dishwashing area, left fixture	3/13/2024	0732	22.5	Replace lead containing components and retest per statutory requirements
11	11-GLAB-F-K-W-R	Faucet	Kitchen	West wall of dishwashing area, right fixture	3/13/2024	0733	9.91	Replace lead containing components and retest per statutory requirements
12	12-GLAB-IM-K	Ice Maker	Kitchen	Mid west wall of kitchen	3/13/2024	0735	<1.00	No remediation required. Monitor per statutory requirements.

MSU: Greenwood Lab School (GLAB)

Sample #	Sample ID	Outlet Type	Location	Location Specific	Initial Sampling Date	Initial Sampling Time	Lead Results	Remediation
							200.8 Method ug/L (ppb)	
13	13-GLAB-F-K-HW	Faucet	Kitchen	Handwashing sink near kitchen restroom	3/13/2024	0739	6.14	Replace lead containing components and retest per statutory requirements
14	14-GLAB-WF-311	Water Fountain	300 Hallway	Outside of room 311, bubbler	3/13/2024	0744	<1.00	No remediation required. Monitor per statutory requirements.
15	15-GLAB-WF-300/500-L	Water Fountain	Corner of 300/500 Hallway	Between restrooms, left fountain	3/13/2024	0750	<1.00	No remediation required. Monitor per statutory requirements.
16	16-GLAB-WF-300-500-R	Water Fountain	Corner of 300/500 Hallway	Between restrooms, right fountain	3/13/2024	0751	<1.00	No remediation required. Monitor per statutory requirements.
17	17-GLAB-F-CONC	Faucet	Concessions area	South wall, basin sink	3/13/2024	0705	<1.00	No remediation required. Monitor per statutory requirements.
18	18-GLAB-F-CONC	Faucet	Concessions area	North wall, handwashing sink	3/13/2024	0706	<1.00	No remediation required. Monitor per statutory requirements.
19	19-GLAB-WF-700-L	Water Fountain	700 Hallway	Near restrooms, left fountain	3/13/2024	0756	<1.00	No remediation required. Monitor per statutory requirements.
20A	20A-GLAB-WF-700-R	Water Fountain	700 Hallway	Near restrooms, right fountain, bottle filler	3/13/2024	0758	<1.00	No remediation required. Monitor per statutory requirements.
20B	20B-GLAB-WF-700-R	Water Fountain	700 Hallway	Near restrooms, right fountain, bubbler	3/13/2024	0757	<1.00	No remediation required. Monitor per statutory requirements.
21A	21A-GLAB-WF-600-L	Water Fountain	600 Hallway	Between locker rooms, left fountain, bubbler	3/13/2024	0800	<1.00	No remediation required. Monitor per statutory requirements.
21B	21B-GLAB-WF-600-L	Water Fountain	600 Hallway	Between locker rooms, left fountain, bottle filler	3/13/2024	0801	<1.00	No remediation required. Monitor per statutory requirements.
22	22-GLAB-WF-600-R	Water Fountain	600 Hallway	Between locker rooms, right fountain	3/13/2024	0802	<1.00	No remediation required. Monitor per statutory requirements.
23	23-GLAB-WF-311-BF	Water Fountain	300 Hallway	Outside of room 311, bottle filler	3/13/2024	0745	<1.00	No remediation required. Monitor per statutory requirements.

Total: 29

* Sample #4B not sampled, fountain was bubbler only