

MSU: Childhood Development Center (CDC)

Sample #	Sample ID	Outlet Type	Location	Location Specific	Initial Sampling Date	Initial Sampling Time	Lead Results	Remediation
							200.8 Method ug/L (ppb)	
1	01-CDC-WF-ENT-L	Water Fountain	Near Entrance	Between restrooms, left fountain	3/13/2024	0601	<1.00	No remediation required. Monitor per statutory requirements.
2	02-CDC-WF-ENT-R	Water Fountain	Near Entrance	Between restrooms, right fountain	3/13/2024	0601	<1.00	No remediation required. Monitor per statutory requirements.
3	03-CDC-F-180-UP	Faucet	Room 180	South wall of room, upper sink	3/13/2024	0603	<1.00	No remediation required. Monitor per statutory requirements.
4	04-CDC-F-180-LOW	Faucet	Room 180	South wall of room, lower sink	3/13/2024	0604	<1.00	No remediation required. Monitor per statutory requirements.
5	05-CDC-F-183-UP	Faucet	Room 183	East wall of room, upper sink	3/13/2024	0606	<1.00	No remediation required. Monitor per statutory requirements.
6	06-CDC-F-183-LOW	Faucet	Room 183	East wall of room, lower sink	3/13/2024	0607	1.2	No remediation required. Monitor per statutory requirements.
7	07-CDC-F-183-W	Faucet	Room 183	West wall of room	3/13/2024	0608	<1.00	No remediation required. Monitor per statutory requirements.
8	08-CDC-F-185-E	Faucet	Room 185	East wall of room	3/13/2024	0609	<1.00	No remediation required. Monitor per statutory requirements.
9	09-CDC-F-185-W	Faucet	Room 185	West wall of room	3/13/2024	0611	1.25	No remediation required. Monitor per statutory requirements.
10	10-CDC-F-185-N	Faucet	Room 185	North wall of room	3/13/2024	0612	<1.00	No remediation required. Monitor per statutory requirements.
11	11-CDC-F-K-HW	Faucet	Kitchen	South wall, handwashing sink	3/13/2024	0614	<1.00	No remediation required. Monitor per statutory requirements.
12	12-CDC-F-K-N	Faucet	Kitchen	North wall, basin sink, faucet	3/13/2024	0616	<1.00	No remediation required. Monitor per statutory requirements.
13	13-CDC-SPRAY-K-N	Faucet- Sprayer	Kitchen	North wall, basin sink, spray attachment	3/13/2024	0617	<1.00	No remediation required. Monitor per statutory requirements.
14	14-CDC-DW-L	Dishwasher	Kitchen	North wall, left dishwasher	3/13/2024	0620	<1.00	No remediation required. Monitor per statutory requirements.
15	15-CDC-DW-R	Dishwasher	Kitchen	North wall, right dishwasher	3/13/2024	0622	<1.00	No remediation required. Monitor per statutory requirements.

MSU: Childhood Development Center (CDC)

Sample #	Sample ID	Outlet Type	Location	Location Specific	Initial Sampling Date	Initial Sampling Time	Lead Results	Remediation
							200.8 Method ug/L (ppb)	
16	16-CDC-F-282-E-UP	Faucet	Room 282 (Second Floor)	East wall of room, upper sink	3/13/2024	0632	1.33	No remediation required. Monitor per statutory requirements.
17	17-CDC-F-282-E-LOW	Faucet	Room 282 (Second Floor)	East wall of room, lower sink	3/13/2024	0633	1.22	No remediation required. Monitor per statutory requirements.
18	18-CDC-F-282-W	Faucet	Room 282 (Second Floor)	West wall of room	3/13/2024	0634	1.11	No remediation required. Monitor per statutory requirements.
19	19-CDC-F-288-E	Faucet	Room 288 (Second Floor)	East wall of room	3/13/2024	0630	<1.00	No remediation required. Monitor per statutory requirements.
20	20-CDC-F-288-W-UP	Faucet	Room 288 (Second Floor)	West wall of room, upper sink	3/13/2024	0627	<1.00	No remediation required. Monitor per statutory requirements.
21	21-CDC-F-288-W-LOW	Faucet	Room 288 (Second Floor)	West wall of room, lower sink	3/13/2024	0628	2.26	No remediation required. Monitor per statutory requirements.